Bungalow Inspections

Property Inspection Report



12345 Your Street , Zephyrhills, FL 33542 Inspection prepared for: 4-Point Sample Real Estate Agent: -

Date of Inspection: 4/16/2025 Time: 8:30 AM Age of Home: 1978 Size: 884 Weather: Sunny 65 Order ID: 5948

Inspector: Shaun Douglas 7241 Drifting Sand Dr, Westly chapel, FL 33544

Email: shaun@bungalowhomeinspections.com BungalowHomeInspections.com



4-Point Inspection Form

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Forced Air Electric Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: Unknown					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No Space heater used as primary heat source? ☐ Yes ☒ No Is the source portable? ☐ Yes ☒ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☒ No					
Supplemental Information Age of system: 12 years Year last updated: 2013 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System Is there a temperature pressure relief valve on the water heater? Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage 2009 year model					
General condition of the following plumbing fixtures and connections Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
Supplemental Information					
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below) New Hot and cold cpvc and pex lines. date of renovation unknown.	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form</i> .)						
Predominant Roof Covering material: _Asphalt shingles Roof age (years): _Less than_1 \cdot ? Remaining useful life (years): _20 years Date of last roofing permit: _3/25/25 Date of last update: _3/25/25 If updated (check one): Full replacement	Date of last roofing Date of last update: If updated (check or Full replacement Partial replacement % of replacement	fe (years): permit: ne): nt				
Overall condition: Satisfactory Unsatisfactory (explain below)	Overall condition: Satisfactory Unsatisfactory	(explain below)				
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No	(check all that apply	nule loss ralt /cracked tabs or tiles lecking mage of leaks? Yes No ecking Yes No				
Additional Comments/Observation	ns (use additional pages if needed	d):				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
Owner	-Inspector HI-10277	4/16/2025				
Inspector Signature Title	License Numbe	r Date				
Bungalow Inspections LLC FI Home	e Inspector 813-400-5294 e Type Work Phone					

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

4 Point Photos

1. Photos

Appear Minor Moder Major Safety
s Concer ate Concer Concer
Servic n Concer n n

	1	-	1
		4	
	1	100	























































Page 6 of 9





















































Photos



cool mode